


Do not update the inverter if the firmware version on board is equal to or greater than the one on the **ZCS Azzurro** website



Firmware version on board the inverter
(to be compared with the one on the ZCS Azzurro website)

[Firmware HYD 3000 6000 ZSS HP V30050 00 50](#)



*The downgrade could bring
to the device lock*

[Firmware HYD 3000 6000 ZSS HP V40012 00 12](#)

